

No.5, Industrial 1st Rd., Lin-Yuan, Kaohsiung, Taiwan

TEL: 886-7-641-3201 FAX: 886-7-641-4544



SAFETY DATA SHEET

DATE ISSUED: 04/11/03 DATE REVISED: 01/06/2016 REV. No.: 007

1. COMPANY IDENTIFICATION

PRODUCT NAME :3100R \cdot 1000 \cdot 1000T \cdot 1003 \cdot 1250 \cdot 3000 \cdot 3000D \cdot 3100 \cdot 3100M \cdot

3000H \cdot 3000P \cdot 5000 \cdot 5000S \cdot 5000F \cdot 3000K \cdot 3100H \cdot 6000 \cdot

6000F · 6000P · 6000R · 6000S · 5000W · 5000M · 3100S · 3100F ·

1000M · 3100K

SUPPLIER :TAITA CHEMICAL CO. LTD., / KAOHSIUNG BRANCH

COMPANY ADDRESS: No.5, Industrial 1st Rd., Lin-Yuan, Kaohsiung, Taiwan

TELEPHONE: 886-7-7040988 EXT 1355 FACSIMILE: 886-7-6414544 EXT 1355

2. HAZARD IDENTIFICATION :

GHS classification:

This product is not hazardous under United Nations GHS Parts 2,3 and 4.

Most Important Hazards None
Adverse Human Health Effects None
Environmental Effects None
Physical and Chemical Hazards None

3. COMPOSITION / INFORMATION ON INGREDIENTS

PRODUCT DESCRIPTION : Acrylonitrile-Butadiene-Styrene copolymer

PRODUCT IDENTIFIER : TAITALAC ABS

Content : 100%

Formula : $(C_3H_3N)_x - (C_4H_6)y - (C_8H_8)z$

CAS No. : 9003-56-9

4. FIRST AID MEASURES

Eye Contact: In case of pellets or powder, flush with plenty of water for at least 15 minutes.

Seek medical advice if any dust particles still remain. In case of gases evolving from melted resin of high temperature, flush with plenty of water for at least 15 minutes.

Seek medical advice if necessary.

Skin Contact: Wash skin thoroughly with soap and water. Seek medical attention if rash or burn



No.5, Industrial 1st Rd., Lin-Yuan, Kaohsiung, Taiwan

TEL: 886-7-641-3201 FAX: 886-7-641-4544



Induce vomiting. Rinse mouth with water. Seek medical advice if necessary.InhalationIn case of gases evolving from melted resin, move subject to fresh air. Treat

symptomatically.

5. FIRE FIGHTING MEASURES

Extinguishing Measures: At the time of fire, high heat as well as gases containing dense black

smoke, carbon dioxide, carbon monoxide, nitrogen oxides, etc. are

generated. At the time of fire-fighting, wear proper protective clothing and

respirators.

Extinguishing Media: Water, water spray, and various kinds of fire-extinguishers may be used.

Special Fire-Fighting Procedure: Self contained breathing apparatus.

Fire and Explosion Hazards: None

6. ACCIDENTAL RELEASE MEASURES

Environmental Precautions: In case it is spilled on the road or floor, there is danger of slipping

and falling. Thus, collect the spilled pellets and dispose of them. If it is accidentally released, it may cause environmental contamination, so

immediately collect all that have been released.

Methods for Cleaning up: Recovery if not contaminated or Disposal

7. HANDLING AND STORAGE

Handling: Gases and fumes in the drying and molding process may cause irritation to the skin

and respiratory tract. Prevent contact with skin and eyes. Use industrial hygiene

practices. Provide adequate ventilation. Secondary operation such as grinding, sanding

or sawing may produce a dust explosion hazard. Use aggressive housekeeping activities to prevent dust accumulation; employ bonding, grounding, venting and

explosion relief provisions in accordance with accepted engineering practices.

Storage: Store in a dry place away from moisture, excessive heat and sources of ignition.

Avoid direct sunlight. To avoid risk of collapse, do not stack unsupported boxes too

high.

8. EXPOSURE CONTROLS/PERSONAL PROTECTION

Threshold Limit Value : Not determined

Ventilation : Necessary to exclude dust, fumes and gases.



No.5, Industrial 1st Rd., Lin-Yuan, Kaohsiung, Taiwan

TEL: 886-7-641-3201 FAX: 886-7-641-4544 MSDS-ABS Ver.: 7.0 TAITALAC ABS Resin

PERSONAL PROTECTION:

Eye: Wear safety glasses for general purpose. Wear chemical goggles for cleaning molding machines.

Skin: When handling pellets avoid prolonged or repeated contact with skin, there is no special need of gloves, But when handing molten resins, wear gloves having good Thermal insulation. Ordinary work clothing will do, but in case of handling molten resins, wear work clothing having long sleeves.

Respiratory: Wear masks for cleaning molding machines.

9. PHYSICAL AND CHEMICAL PROPERTIES

Apperance : Milky off-white Solids

Melting Point : Softening above 100 °C

Vapor Pressure (mmHg) : None

Specific Gravity :1.03-1.08

Solubility : Insoluble in water

Volatility : None

10. STABILITY AND REACTIVITY

Flashing Point :400°C

Auto Ignition Point :466°C.

Upper Explosion Limit : None

Lower Explosion Limit : None

Stability : Stable under recommended conditions of storage and handling

Reactivity with Water : No :Yes
Flammability : Explosive

Dust Explosiveness : CO, HCN, AN, SM and NO

Thermal Decomposition Gases

11. TOXICOLOGICAL INFORMATION

Irritation: Fumes or vapors generated from decomposing resin may be irritant to eyes.

Acute Toxicity (Includes 50% Lethal Dose) : Oral LD $_{50}$ (Rat) > 5g/kg (Assumed Value)

Sub-Acute Toxicity: No Information

Mutagenicity: Not determined.



No.5, Industrial 1st Rd., Lin-Yuan, Kaohsiung, Taiwan

TEL: 886-7-641-3201 FAX: 886-7-641-4544 MSDS-ABS Ver.: 7.0 TAITALAC ABS Resin

12. ECOLOGICAL INFORMATION

To avoid being taken by ocean species or birds, disposal of the waste to the ocean and water sources is inhibited.

13. DISPOSAL INFORMATION

It shall be handled in accordance with the laws, rules, and ordinances related to the disposal of waste matters.

14. TRANSPORTATION INFORMATION:

Not classified.

15. REGULATORY INFORMATION:

Not available.

16. OTHER INFORMATION:

None.